

**0018** **Technical Service Information****Subject:** Integrated rotary shaft seals**Relates to:** 81-90006-00
81-90010-00
81-90016-00
81-90018-00**Make:** Volkswagen, Audi, Seat, Skoda**Model(s):** Various**Engine code:** Various**Integrated rotary shaft seal -
installation information**

Dear Customer,

The rubber coating underneath the integrated rotary shaft seals has no sealing function [Fig. 2]. For this reason, the application of additional sealing compound or a corresponding oil sump gasket is necessary during replacement.

This means that the oil sump always needs to be detached and newly re-sealed whenever the integrated rotary shaft seals are replaced.

Yours faithfully,
Your Victor Reinz® Service Team



Figure 1_Integrated rotary shaft seal 81-90006-00



Figure 2_Underside of the integrated rotary shaft seal

Victor Reinz® – the best way to get a good gasket.