


## **PI 0023** For technical personnel only!

Page 1/1

## **PRODUCT** INFORMATION

## Modification of cylinder liners for OM 501/502

Engine manufacturer: Mercedes-Benz	i   ,		
Engine series	OM 501 LA	OM 541.920 - 541.927 4V Euro 2	(six-cylinder engine)
	OM 502 LA	OM 542.920 - 542.926 4V Euro 2	(eight-cylinder engine)
	_		
		12	



The engine manufacturer has modified the cylinder liner design.

The cylinder liner 89 473 110 used to date for Euro-2 engines without cooling channel is being replaced in the course of this product update by cylinder liner with KS number 89 594 110. The cylinder liners supplied up till now can however still be used up.

Ordering information	KS No.
Cylinder liners for engine block without cooling channel (Euro-2 engine only) Cylinder liner: <b>old (is no longer applicable !)</b> <b>new</b>	(89 473 110) 89 594 110
Cylinder liners for engine block with cooling channel (Euro-2 engine only)	
Cylinder liner: (no change)	89 530 110

The right of changes and deviating pictures is reserved. For exact details about applications, please refer to our current catalogue / CD / OnlineShop.

## www.ms-motor-service.com

MS Motor Service International GmbH · 74196 Neuenstadt · Germany Kolbenschmidt Pierburg Group

